	^		
		n	

6.8

### ROUTING AND RECORD SHEET

INSTRUCTIONS: Officer designations should be used in the "To" column. Under each comment a line should be drawn across sheet and each comment numbered to correspond with the number in the "To" column. Each officer should initial (Check mark insufficient) before further routing. This Record and Routing Sheet should be returned to Registry.

		M			
FROM: [		, OPS-	a/s-II	29 May	50 NO.
Room 1412 -	Building	, K - Ex	t: 666	, , ,	5-24941
HOOM TAIL	DULLULIE	5 11	• 000		
					comments 1450
	ROOM	DA	ATE.	OFFICER'S	COMMENTO
то	NO.	REC'D	FWD'D	INITIALS	COMMENTS
		IN E O			
chief	1308	ľ			162:
Area I, FBE	K				Recommend we accomme
711 00 1, 102	1				
<sup>2</sup> . م	1			_	tt grunay. Set's so
					- almost with the an amount
				レ	
3•	-				an the sub-quiect is improved,
					we chald send the up to
4.					[ ] with a count
	-				manns. cetting first war
		,			
5•					reconnection,
6.					5/3/
					ma on the later
					2 to 1 -L Dis cleared this
7.					2 to 1 - C Jis cleared this  date and will proceed to  Gloucester Mass when the hanges in Para 4.
•					date and will proceed a
					Clourester Mass when his wiret
8.					There have to cake with the denotes
					in rara 4.
9•	-	<del> </del>			Chelen
					G/15/50
					2 to 1 - The Sub-project Baspeed
10.		<del> </del>			
U	ECLASSIF	EDAND	RELEASE	עם ת	
v	' -   P   R   A   L	RILLIE	ANCE VOS	MAM	date -
3	UURLESME	TUARCEVI	H 14 m = 1 m	RLY	
И.	AZI WAR CR	INECOLA	EMPIIUN 3	RIB	6/15/50
Ð	ATE 2007	וטפשיין	CLOSURE	ACT	
	7 2 2 0 0 /	<b> </b>	<del> </del>		this date a will proceed with me to Glovester on Monday
12.					this date or will prouged with me
					Les de la company de la compan
					to Gloveester on Monday 7
13.					
	1				
14.					
					,
15.					
			1		

26 May 1950


MEMORANDUM FOR: Chief, Foreign Branch E, Area I

SUBJECT

: Project BCFIEND - Survey of proposed propaganda vessels - yachts, IRMAY and SERVA LE BARI.

- 1. The subject vessels were inspected by Commo, and 7, Staff II, MSO on 23 and 24 May 1950 in accordance with your request dated 2 April 1950.
- 2. After a careful inspection, it was found that both vessels are considered to be suitable for the mission at hand. The opinion of the survey team is that the motor sail/ketch IRMAY is the most adaptable from the point of view of broadcast requirements, maneuverability, accommodations for the crew and staff and can be outfitted in the least time and expense.
- 3. Detailed comparison of both vessels as to their suitability is covered by Annex I. Annex II is a description of the IRMAY and Annex III is a description of the SERVA LE BARI.
- l. It appears that the owners of both vessels give as their reason for selling, matrimonial difficulties (wives refuse to be yacht widows). The Captain of the IRMAY indicated that Mr. Irwin Cohn, the owner, is of a very changeable nature and, therefore, if negotiations are contemplated, action should be started immediately. It is further suggested that an offer of about \$75,000 may result in closing the purchase at a figure in the neighborhood of \$80,000 to \$85,000. The purchase should be contingent upon a thorough inspection "on the ways" by a competent marine engineer and/or Naval architect. It will require at least 14 days notice to the owner to arrange for this, cost to be borne by the purchaser. The IRMAY at present is insured by the Atlantic Mutual, 49 Wall Street, New York City, for full coverage anywhere in the world.
  - 5. With respect to the SERVA LE BARI, Mr. Crockett, the owner, indicated that he can place the vessel "on the ways" for inspection on a 72 hour notice. In view of the more extensive alterations required to out fit the BARI for the mission, it is suggested that the offer price should be somewhere in the neighborhood of \$50,000 and the closing price between \$55,000 and \$60,000. Mr. Crockett stated that he would not be willing to set the vessel "on the ways" unless we were reasonably sure of the sale which would only be subject to the inspection contingency. He offered to cover this expense.
  - 6. In the case of either vessel, if any additional gear, equipment or personnel over and above the requirements set forth in the original request is contemplated, it should be fully realized that the present accommodations will be inadequate and a larger vessel will be required.

- 7. The Captain of the IRMAY and the present crew are available for employment. They appear to be efficient and experienced and have, in the past, accompanied several scientific expeditions to the Caribbean and South American waters. Annex IV is a list of the crew and their qualifications.
  - 8. The undersigned recommend the procurement of the IRMAY.





4 Incl

Annex I - Comparative data on BARI and IRMAY

Annex II - Description of IRMAY

Annex III - Description of SERVA LE BARI

Annex IV - List of IRMAY crew & their qualifications

#### Distribution:

1 - Chief, Area I, Foreign Branch E ( )

2 - OPS-M/S-II Working file on Project BGFIEND

3 - Chief, Foreign Branch E, OPC ( )

4 & 5 - OPC Registry

S-II/E J/EJ

### ANNEX I.

	BARI	IRMAY	
Range Speed (cruising) Max. Fuel Capacity Water Capacity	World 8 mph. 1,500 2,500	3,000 13 mph. 3,200 2,000	
Adequate Refrigeration Plant Heating Plant Heating Fuel Cooking Fuel Engine Fuel Engine Type	Yes CirHot Water Sys. Coal Coal Oil Single Fairbanks	Yes CirHot Water Sys. Tank Gas Tank Gas Oil Twin Buda	Recommend overhaul of
Accommodations (total) Berths State Rooms Radio-Present Radio-Generator	Morse  15 15 4 Yes None	13 12 5 Yes None	engines. All sleeping accommodations should be rearranged.  "  AC power plant must be installed in both vessels. Major work for the AC gen-
Mast Heights	87'-77' Ample	78'-62' Enough	erator and studio required on BARI. BARI between Masts - 25' IRMAY between Masts - 39' 20 ft. mast extension desirable and practicable on IRMAY.
Mast Suitability Space Suitability	Yes	Yes	Both vessels require space
for Antenna	Yes	Yes	change for radio station and work area. IRMAY re- quires least remodeling.
Modifications (Installation Radio) Vibration	Yes Unknown	Yes Yes	IRMAY requires new stern bearings (rubber) to reduce vibration.
Crew required Special Skill Captain - Special	7 6	<u>l</u> . 2	reduce Albracion.
Skill Yacht - Type	Yes No	No Yes	

ANNEX I (con't)

	BARI	IRMAY	
Fame of Vessel	Well known	Only two of this type	
Profile	Common	Rare	
Maneuverability	Poor	Excellent	
Hull	Steel	Wood \ IRMAY requires copper sheeting for broadcast installation.	
Auto. Pilot Availability	No	Yes	
for Voyage	4 wks.	Presently	

IRMAY - ENGINE SPECS (BUDA LUNOVA DIESECS)

PORT

# 6LDMR-17420-3115

DILLO B/M

DILLO B/M


DILLO B/M

D1116 B/M

BURZ: 6; "

STROKE 8; GOV. SPEED 1100 R.P.M

6 2 8 3 1100 RPM



YACHT BROKER SALES - CHARTERS

Designer....

Fastenings.....

Staterooms: Single

Truck Sillism

No. Berths or Extens, in Saloon

SERVA LA BARI

Type and Rig Auxiliary Gaff Schooner

Dutch State Dock Yard Helder, Holland

Ballast: If Lead or Iron (about 50 tons)

Trunk Cabin Flush - Deckhouses
Raised or Flush Deck Plush - Deckhouses
Modified

Clipper

None

Interior Finish Mahog & Redwood

Keel

9210"

20 '10"

Boele Bolnes

#### GORDON RAYMOND

Yea 1923

81'0"

10'8"

Planking Steel (3/8")

Style of SternCounter

Headroom Full

Three

Nine

Three

Natural

420 LEXINGTON AVENUE NEW YORK 17, N. Y.

TELEPHONE: OREGON 9-2262

APPRAJSALS - SURVEYS DESIGN CONSULTANT

Designed and

202 FILE NO. Air-Injection) Iwin os ingle Fairbanks-Morse Single. Cylinders Six .Year 1948 Gas oDiesel 7-8 kn H. P. (eq. 100 2500 Total Capacitkw Hercule: Generator plus 3 kw on How Lighted Lectric (110v) engine Heating Plant Hot Water electric & <sup>R</sup>්ක් ප්රේක්ෂ්ය අද ක්ර Sails, Makers, Age and Cooney 1947 & 1949 plus others of unknown 6000 make 19**68 - very good** Standing Rigging: Age Md & the 1923 Hollow Steel others Wood-some 1948 Spars: Age, Hollow of Solid The Sailing dinghy; I lifeboat; & 1 work boat ample Two ample 1 & shower Crew Accommodations yes Whether Yacht is Fully Found. LOCATION

PHOTOGRAPH

Rath 2 (Showers)

REMARKS: (Condition, Seaworthiness, Speed, Furnishings, Equipment, Etc.)


ASKING PRICE


CHARTER PRICE

Built for keeping to sea for long periods. A very able seaboat - the finest of her type available today. Heavily built of the finest materials. Entire vessel given extensive overhaul 1947 & 1948. --- New steel deckhouse added. Four watertight steel bulkheads (watertight doors in two). High Entire vessel acoustically & steel bulwarks. thermally insulated. Hot and cold fresh and salt pressure water systems. New electric system including control panel. Emergency air and bilge pumps. Elec. anchor windlass. Complete navigation equipment. Radio direction finder. Radio telephone. Fathometer. All wave radio broadcast receiver. Large galley equipped with AGA coal range. Large yard and squaresail on foremast.

SUBJECT TO PRIOR SALE, COMMITMENT, WITHDRAWAL OR CHANGE IN PRICE WITHOUT NOTICE

PARTICULARS AS CORRECT AS CIRCUMSTANCES PERMIT, BUT NOT GUARANTEED.





ANNEX IV.

Present Crew of IRMAY

Captain: Matthew English

Beacon Marine Basin c/o Yacht IRMAY Gloucester, Mass.

Age: 31

Married, no children

Experience: 13 years. He was a captain and first mate in the Army

Transport Service on sea-going tugs during the war. Also served as captain for several private yachts in addition to the IRMAY. He has a very pleasing personality, appeared

to be most competent and displayed excellent skill in

handling the vessel during the trial run.

First Mate: Richard Roming

Beacon Marine Basin c/o Yacht IRMAY Gloucester, Mass.

Age: 26

Single

Experience: Served with the USCG during the war, considered by the

captain to be fully qualified as navigator and has a

thorough knowledge of the plant of the IRMAY.

Engineer: James C. Kuhn

132 Truxon Drive

Miami Springs, Florida

Age: 23

Single

Experience: Two years in the USCG, rating Motor Machinest 3rd class,

experience gained in diesel shops in the Miami area. Displayed intimate technical knowledge of the IRMAY's

power plant and assisted on deck.

Cook: Thomas Anderson

Age: 60

Single

Experience: This man has followed the sea his entire life, is considered

to be an excellent cook and served in that capacity on various

ANNEX IV. (con't)

vessels of the U. S. Army Transport Service during the war. He has no permanent address other than the IRMAY but maintains a mailing address at the Cornish Arms Hotel, New York. He appeared very rugged and a most pleasant individual. He has acquired the ability to get along with people regardless of their station of life.

YACHT BROKER SALES - CHARTERS

#### GORDON RAYMOND

.420 LEXINGTON AVENUE NEW YORK 17. N. Y.

TELEPHONE: OREGON 9-2262

APPRAISALS - SURVEYS DESIGN CONSULTANT

2001

FILE NO.

lame of Yacht IR	MAY ex-	HORMAC	ex-VAI	ERIE V
Tw1	n screw	Diesel	Marco	n1
eel or C. B				
esigner WM.	H. Hand	1, Jr.		
uilt by	H <b>od</b> gd <b>o</b> n	Bros.		Y. 1939
. O. A	91'		83'6'	)
eam	81,	Draft	916'	
onnage Gross	184		Net	84
alläst: If Lead or I	ron 10	ead ins	ide	
rames of whi	te oak	Plankin	g of doub	le pine
astenings <b>BALV</b>	AI) . Finish o	en f Decks na	tural	teak
runk Cabin aised or Flush Decl				
tyle of Bow 11	sherman	Styl	e of Stern	ransom
ize of Cockpit	none		elf-Bailing	
nterior Finish <b>CP</b>	an & mal	nog.	Headroom	71
taterooms: Single	1		Double	3
io. Berths or Extens	. in Saloon	1		
.ccommodations, To				
lo. Showers or Batl				
io. anowers or Bati	15	NO. I	O11615	

Bu <b>da</b>		Twin or	twin
Make of Engine(s)		Single	04 711
Gas or Diesel Cylinders	6	Year	1939
4-cycle 200 Red Gear Yes			
io. Fuel Tanks	Total (	Capacity	3,200 g
lo. Water Tanks			0 000
low Lighted electric			
yes			
iails, Makers, Age and Cond. Beckme	ın 19	39 🚡	good
ans, makers, Age and Jonassian	***************************************	***************************************	
		Sa. 1	1721
tanding Rigging: Age and Cond.	) g <b>o</b> o	đ	
19	a 086	0114	
mall Boots davits; I life	raft		
Anchors 4 Septime	aple	Cablo	ample
4 bertis	•••••	Саыте	
rew Accommodations 1 stater(	Om	Toilets'	T & SUOM
Whether Yacht is Fully Found	уев		
	- J. g. ***	ş.; .	W.Y.

PHOTOGRAPH

REMARKS: (Condition, Seaworthiness, Speed, Furnishings, Equipment, Etc.)

Exceptionally able seaboat; heavy construction;

large cruising redius.

atteries 1949; 75-watt radio-telephone;
ection finder; electric anchor windlass;
old pressure water system; automatic pilot
ladeast receiver; automatic phonograph; inaications system. Very attractively arrangbs staterooms; large dining salcon and main
an deckhouse - 15! x 15!).

OR SALE, COMMITMENT, WITHDRAWAL OR CHANGE IN PRICE WITHOUT NOTICE

YACHT BROKER SALES - CHARTERS

### GORDON RAYMOND

420 LEXINGTON AVENUE NEW YORK 17, N. Y.

TELEPHONE: OREGON 9-2262

APPRAISALS - SURVEYS DESIGN CONSULTANT

8001

Name of Yacht IRMAY ex-MORMAC ex-VALERIE V	Buda Twin or twin  Make of Engine(s)
Type and Rig Twin screw Diesel Marconi ketch-rigged Motor Sailer	Gas or Diesel Cylinders 6 Year 1939
Ketch-rigged Motor Sailer  Keel or C. B. Keel	4-cycle H. P. (ea. 200 Red Gear Yes Speed 13 mph
Designer	No. Fuel Tanks
Built by Hodgdon Bros. Yeal939	No. Water Tanks
LO.A. 911 /LW.L 8316#	How Lighted electric Generator Heroules Di
211 916" Beam	Heating Plant Yes Refrigeration Refrigeration
Tonnage Gross 184 Net 84	Sails, Makers, Age and Cond. Beckman 1989 - good
Ballast: If Lead or Iron lead inside	
Frames of White oak Planking of double pine	1721 
Fastenings Ralvan. Finish of Decks natural teak	Standing Rigging: Age and Cond.
Trunk Cabin Raised or Flush Deck trunk cabin - deckhouse	Summa Ann Hallow or Solid 1939 solid
Style of Bow fisherman Style of Stern transom	I indeard and I cutboard both I
Size of Cockpit <b>none</b> If Self-Bailing	Anchors & Shain the Cable ample
Interior Finish oream & mahog. Headroom 71	Crew Accommodations 1 stateroom Toilets 1 & showe
Staterooms: Single	Whether Yacht is Fully Found
No. Berths or Extens. in Saloon	LOCATION CARRIED W.Y.
Accommodations, Total 8	ASKING PRICE S / 60, 60
1 tub No. Showers or Boths 2 showers No. Toilets electric	CHARTER PRICE CREW


**PHOTOGRAPH** 

REMARKS: (Condition, Seaworthiness, Speed, Furnishings, Equipment, Etc.)

Exceptionally able seaboat; heavy construction; extremely large cruising radius.

New batteries 1949; 75-watt radio-telephone; radio direction finder; electric anchor windlass; hot and cold pressure water system; automatic pilot; radio broadcast receiver; automatic phonograph; intercommunications system. Very attractively arrange w/spacious staterooms; large dining salcon and main lounge (in deckhouse - 15' x 15').

SUBJECT TO PRIOR SALE, COMMITMENT, WITHDRAWAL OR CHANGE IN PRICE WITHOUT NOTICE PARTICULARS AS CORRECT AS CIRCUMSTANCES PERMIT, BUT NOT GUARANTEED.



FILE MO 1646

YACHT SALES & SERNCE, INC.,
PHILADELPHIA S.PA.

Atu Bearing be cheek-replace ente Rubber Capt James Dr. English 31-married Beacon manne Basin Mass. 2 Imay-Cyperience -14 years Pourter Mass. 2 Imay-H. W. Cannon Je - 5 yrs but ahem that army Transport - 1st officer & Coph. Mys Trus P. Pomeranty - 1 yz. D. 4. Truis Cohn - 4yrs. 55 mall St. Titelbury -Tal- 5300-

Recommend installation & built in bunks in crews quarter